




Instruction for

- Adding additional cutting tools




- 1) Draw any image on the screen first and then click on a tool path.



- 2) Click on the small box with 3 dots on the right side of the tool description.



- 3) Enter a new name for the tip. For Ex. Wax Cutting Tip with 10 Degrees angle. Change the angle and lower the Diameter 2. Click ADD to finalize the addition.



The accuracy of the Tool path drawings will improve with correct settings. Efficiency of the cutting and longevity of the cutter will also improve.